# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

CENTER Corner of Section 17 W, Township 102 N, Range 18 W, 5 P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

On 7-3-90 found A STONE UNDER CONC. MONUMENT, REMOVED CONC. MONUMENT

☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)

On 7-9-90 placed A 1/2" PIPE

SKETCH OF REFERENCE TIES




Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald J. Olson — Signature
7-13-90 — Date

Registration No. 11009

☒ Land Surveyor ☐ Prof Engineer
☐ County Surveyor ☐ County Engineer


Zenk·Read·Trygstad & ASSOCIATES, INC.
Engineers / Architects / Land Surveyors / Planners
Box 689, Albert Lea, MN 56007 507/373-0689


OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Recorders office at _____ .M. on the ____ day of _____ A.D., 19__.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

CENTER QUARTER CORNER SECTION 17, TOWNSHIP 102 NORTH, RANGE 18 WEST, 5TH P.M.

1967 — Page 15 of the Mower County Surveyors Record shows a Concrete Monument inplace. See also County Engineers Road Plans 1967.

July 2, 1990 — Zenk Read Trygstad & Associates excavated with a backhoe from centerline to 2 feet North by 2 feet East to 6 feet West of Centerline by 3.7 feet deep to natural ground and found a nail over a concrete monument over a stone 3.6 feet below the surface.

An analysis of the record data gives no indication of the origin of the stone. No survey was made to determine the agreement with the intersection of the Quarter Lines.