Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NE Corner of Section 32, Township 102N Range 18W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☒ On 10/15/1991 (DATE) found a CAST IRON MONUMENT

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 1-16-92

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

NE corner Sec 32-102-18

This corner was originally established by Deputy Surveyor Wm. I Anderson of the U.S. General Land Office in 1854. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:

Mower County Highway Dept	Zenk Engineering
Mower County Recorder	Tucker Land Surveying

1930 Mower County Grading Plans shows a monument inplace and the following ties were taken:
- 72.4' East to large Cottonwood Tree
- 49.0' SE to Cottonwood tree
- 48.0' SW to telephone pole
- 44.0' NW to CFP

1945 Recorded in Book "A" in the Office of the County Engineer a monument was found and ties checked with the additional ties taken:
- 122.6' SW to PP
- 123.75' NW to telephone pole

1953 Recorded in Book "A" a concrete monument was found and the following ties were taken:
- 88.8' SW to blazed 12" Oak
- 63.9' SE to spike in CFP
- 68.7' SE to PP
- 129.0' SW to PP

1982 County Grading Plan shows a cast iron monument set over concrete monument during grading project and ties were taken.

1991 Jones, Haugh & Smith Inc crew under the direction of John Schulte IV, dug with the County backhoe and uncovered a cast iron monument set by Mower County Engineering Department after road construction in 1982. At this time this intersection was obliterated during construction and relocated destroying all evidence of public land survey corner or a perpetuation thereof. The monument found is in agreement with ties taken in 1982 when the monument was reset.

The monument fits past records, occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.