Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E1/4 Corner of Section 13, Township 103N Range 15W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-28-93 (DATE) found a 5/8"ø x 18" IRON AND A 6"ø x 18" CONC MON WITH IRON IN CNT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 9-25-96 (DATE) placed a 5/8"ø x 16" IRON

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ 9-27-96
SIGNATURE DATE

Registration No. 15807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19 ___

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

E 1/4 corner Section 13-103-15

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Recorder's Office
Mower County Highway Department
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1885 Clausen, Mower County Surveyor, notes indicate a post at this corner.

1945 Mower County Highway Department, Book 1, indicates a clay tile filled with concrete and an iron in center. Monument was set at the split between northeast corner and southeast corner of Section 13 and also on a straight line.

1993 Jones, Haugh & Smith Inc crew under the direction of John Schulte, RLS 13807, dug a 3'x2'x8' long hole with county backhoe on centerline centerline of County State Aid Highway No. 8 and east-west township roads. We found a 5/8" diameter x 18" iron on centerline centerline of said roads six inches below road surface. Continued digging to a depth of two feet and found a 6" diameter clay tile filled with concrete and a 3/8" diameter iron in center. Concrete monument found was three feet north of centerline of east-west township road and one foot west of centerline County State Aid Highway No. 8. Therefore we discarded 5/8" diameter x 18" iron and accepted concrete monument found which is noted in 1945 Mower County Highway Department notes as the perpetuation of the original public land survey corner. We set a 5/8" diameter x 16" iron near road surface and above concrete monument found.

1996 Jones, Haugh & Smith Crew re-set corner from ties.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E1/4 Corner of Section 13, Township 103N Range 15W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-28-93 (DATE) found a 5/8"ø x 18" IRON AND A 6"ø x 18" CONC MON WITH IRON IN CNT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 6-30-93 (DATE) placed a 5/8"ø x 16" IRON

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 7-13-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 8 P.M. on the 14 day of July A.D., 1993

COUNTY RECORDER Amanda Enger

By Marlene Marten, Deputy

DOCUMENT NO. 122235

Bk 80 Misc Pg 313

M.H.D. FORM NO. 2105 BOOK 80 PAGE 313

STATEMENT OF EVIDENCE

E 1/4 corner Section 13-103-15

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Recorder's Office
Mower County Highway Department
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1885 Clausen, Mower County Surveyor, notes indicate a post at this corner.

1945 Mower County Highway Department, Book 1, indicates a clay tile filled with concrete and an iron in center. Monument was set at the split between northeast corner and southeast corner of Section 13 and also on a straight line.

1993 Jones, Haugh & Smith Inc crew under the direction of John Schulte, RLS 13807, dug a 3'x2'x8' long hole with county backhoe on centerline centerline of County State Aid Highway No. 8 and east-west township roads. We found a 5/8" diameter x 18" iron on centerline centerline of said roads six inches below road surface. Continued digging to a depth of two feet and found a 6" diameter clay tile filled with concrete and a 3/8" diameter iron in center. Concrete monument found was three feet north of centerline of east-west township road and one foot west of centerline County State Aid Highway No. 8. Therefore we discarded 5/8" diameter x 18" iron and accepted concrete monument found which is noted in 1945 Mower County Highway Department notes as the perpetuation of the original public land survey corner. We set a 5/8" diameter x 16" iron near road surface and above concrete monument found.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

BOOK 80 PAGE 314

Revised.

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E1/4 Corner of Section 13, Township 103N Range 15W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-28-93 (DATE) found a 5/8"ø x 18" IRON AND A 6"ø x 18" CONC MON WITH IRON IN CNT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 9-25-96 (DATE) placed a 5/8"ø x 16" IRON

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ SIGNATURE _____ DATE

Registration No. _____

☐ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the ____ day of _____ A.D., 19 ____

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

E 1/4 corner Section 13-103-15

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Recorder's Office
Mower County Highway Department
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1885 Clausen, Mower County Surveyor, notes indicate a post at this corner.

1945 Mower County Highway Department, Book 1, indicates a clay tile filled with concrete and an iron in center. Monument was set at the split between northeast corner and southeast corner of Section 13 and also on a straight line.

1993 Jones, Haugh & Smith Inc crew under the direction of John Schulte, RLS 13807, dug a 3'x2'x8' long hole with county backhoe on centerline centerline of County State Aid Highway No. 8 and east-west township roads. We found a 5/8" diameter x 18" iron on centerline centerline of said roads six inches below road surface. Continued digging to a depth of two feet and found a 6" diameter clay tile filled with concrete and a 3/8" diameter iron in center. Concrete monument found was three feet north of centerline of east-west township road and one foot west of centerline County State Aid Highway No. 8. Therefore we discarded 5/8" diameter x 18" iron and accepted concrete monument found which is noted in 1945 Mower County Highway Department notes as the perpetuation of the original public land survey corner. We set a 5/8" diameter x 16" iron near road surface and above concrete monument found.

1996 Jones, Haugh & Smith Crew re-set corner from ties.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.