Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 21, Township 103N, Range 15W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☒ On 9-8-81 (DATE) found a Cast Iron Quarter Corner Monument

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



Ties are Mn/DOT Copper nails & disks

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

BOOK 55 PAGE 565

Marlow R. McGowan (SIGNATURE) 1-6-83 (DATE)

Registration No. 11527

☒ Land Surveyor, ☒ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of MOWER

I hereby certify that this document was filed in the Co. Recorders office at 2 P. .M. on the 19 day of JAN. A.D., 1983

County Recorder Charles Enger

By Dorothy Johnson, Deputy

DOCUMENT NO. 355584

Book 55 of Misc'l. pg. 565

Mn/DOT 2105 (4-77)

Statement of Evidence:

East Quarter Corner Section 21, T103N, R15W

July 28, 1853	John Quigley, deputy surveyor, set a post in a mound for the corner during the original Public Land Survey.
1930	Minnesota Highway Department found an iron pipe at the intersection of roads east-west and north-south.
1973	Mower County's road plans shows the position of the corner but the type of monument is not indicated.

An analysis of the record and survey data indicates the inplace cast iron monument perpetuates the iron pipe. The origin of the iron pipe is not of record. However, the pipe is in harmony with lines of occupation and has marked the corner for over 50 years.

The cast iron monument is therefore accepted as marking the public land survey corner.

For details of the electronic survey, contact the Surveying and Mapping Section of the Department of Transportation, Rochester.

BOOK 55 PAGE 566