Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SE Corner of Section 13, Township 103N Range 15W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-28-93 (DATE) found a 3/4"ø x 16" IRON AND A 6"ø x 18" CONC MONUMENT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 9-25-96 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 9-27-96

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the ____ day of _____ A.D., 19 ___

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

SE corner Section 13-103-15

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Recorder's Office
Mower County Highway Department
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1885 Clausen, Mower County Surveyor, notes indicate a stone at this location.

1945 Mower County Highway Department, Book 1, indicates a 6" diameter concrete monument with iron in center and a one inch diameter pipe above concrete monument.

1979 Jones, Haugh & Smith Inc crew found a 3/4" diameter pipe at this location.

1993 Jones, Haugh & Smith Inc crew under the direction of John Schulte, RLS 13807, dug a 3'x4'x5' long hole with county backhoe on the centerline of County State Aid Highway No. 8 and inline with east-west line fences. We found a 3/4" diameter x 16" pipe four inches below road surface and a 6" diameter x 18" clay tile filled with concrete and a 3/8" diameter iron in center which was at a depth of four feet and inline with east-west line fences. Therefore we accepted concrete monument noted in above said information as the perpetuation of this corner and set a cast iron monument near road surface above concrete monument found.

1996 Jones, Haugh & Smith Inc crew re-set corner from ties.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

Revised

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SE Corner of Section 13, Township 103N Range 15W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-28-93 (DATE) found a 3/4"ø x 16" IRON AND A 6"ø x 18" CONC MONUMENT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 9-25-96 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ SIGNATURE _____ DATE

Registration No. _____

☐ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

SE corner Section 13-103-15

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Recorder's Office
Mower County Highway Department
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1885 Clausen, Mower County Surveyor, notes indicate a stone at this location.

1945 Mower County Highway Department, Book 1, indicates a 6" diameter concrete monument with iron in center and a one inch diameter pipe above concrete monument.

1979 Jones, Haugh & Smith Inc crew found a 3/4" diameter pipe at this location.

1993 Jones, Haugh & Smith Inc crew under the direction of John Schulte, RLS 13807, dug a 3'x4'x5' long hole with county backhoe on the centerline of County State Aid Highway No. 8 and inline with east-west line fences. We found a 3/4" diameter x 16" pipe four inches below road surface and a 6" diameter x 18" clay tile filled with concrete and a 3/8" diameter iron in center which was at a depth of four feet and inline with east-west line fences. Therefore we accepted concrete monument noted in above said information as the perpetuation of this corner and set a cast iron monument near road surface above concrete monument found.

1996 Jones, Haugh & Smith Inc crew re-set corner from ties.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SE Corner of Section 13, Township 103N Range 15W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-28-93 (DATE) found a 3/4"ø x 16" IRON AND A 6"ø x 18" CONC MONUMENT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-28-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 7-13-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 8:00 P.M. on the 14 day of July A.D., 19 93

COUNTY RECORDER Susanne Engen

By Marlene Marten, Deputy

DOCUMENT NO. 422834

Bk 80 Misc Pg. 311

M.H.D. FORM NO. 2105

BOOK 80 PAGE 311

STATEMENT OF EVIDENCE

SE corner Section 13-103-15

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Recorder's Office
Mower County Highway Department
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1885 Clausen, Mower County Surveyor, notes indicate a stone at this location.

1945 Mower County Highway Department, Book 1, indicates a 6" diameter concrete monument with iron in center and a one inch diameter pipe above concrete monument.

1979 Jones, Haugh & Smith Inc crew found a 3/4" diameter pipe at this location.

1993 Jones, Haugh & Smith Inc crew under the direction of John Schulte, RLS 13807, dug a 3'x4'x5' long hole with county backhoe on the centerline of County State Aid Highway No. 8 and inline with east-west line fences. We found a 3/4" diameter x 16" pipe four inches below road surface and a 6" diameter x 18" clay tile filled with concrete and a 3/8" diameter iron in center which was at a depth of four feet and inline with east-west line fences. Therefore we accepted concrete monument noted in above said information as the perpetuation of this corner and set a cast iron monument near road surface above concrete monument found.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

Index No. p110 "S"

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 24, Township 103N, Range 15W, 5th P.M.

STATE OF MINNESOTA, County of Mower


At the corner location shown on the sketch:

☒ On 10-23-89 (DATE) found a 5" dia. clay pipe 14" long filled with concrete with a 1/2" rod set in the center of the pipe, down 27".

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 10-23-89 (DATE) placed a 3/4" pipe, down 2".

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Signature 12/16/89 (DATE)

Registration No. 1062

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19__

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

Northeast Corner Section 24, Township 103 North, Range 15 West, 5th p.m.

Statement of Evidence:

July, 1853	John Ball, U.S. Deputy Surveyor, set a post and put a hand full of stones in the center for the corner during the Original Public Land Survey.
1938	Mower County Engineering Department used occupation lines for the corner and recorded stationing on the 1938 construction plans.
January 9, 1989	D. Rude and crew dug up a red head nail in bituminous on the occupation lines and temporarily accepted.
October 23, 1989	D. Rude and crew excavated a 3' x 5' area centered on the occupation lines. A 5" dia. clay pipe 14" long filled with concrete with a 1/2" rod set in the center of pipe was found 27" down. A 3/4" pipe was set above the monument, 2" below the bituminous surface. An analysis of the record and survey data show this position agrees with the east-west fence lines, the north-south center-line of county road, and within 4' west and south of lost position. Distances between occupation lines today agreed with 1938 Mower Co. Highway plan distances. The clay pipe is, therefore, accepted as a perpetuation of the Original Public Land Corner and is accepted as marking the Northeast Corner of Section 24. For further information, contact Yaggy Colby Associates, Rochester, Minnesota.