Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E 1/4 Corner of Section 11, Township 103N, Range 16W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 8-27-91 (DATE) found a HARRISON CAST IRON MONUMENT OVER (2) 5/8"ø IRONS

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 8-27-91 (DATE) placed a CAST IRON MONUMENT (Reset)

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ 9-17-91
SIGNATURE DATE

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the ____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

E 1/4 corner Sec 11 T103 R16 established by Deputy Surveyor of the U.S. General Land Office in 1853. The government notes show a wood post and a handful of small stones were set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Dept
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

Book 'A' of the Mower County Engineer's Office show a stake in place. The following ties were taken:
33.9' NE to TP
35.3' E to CFP
105.5' W to culv. post
53.6' SW to Sargeant sign

1982 Jones, Haugh & Smith crew found a 6"x8"x4" split field stone with point up in line with fence east and centerline of north-south road 0.5 feet west. Placed a 5/8" diameter x 24" iron capped 13807 over field stone found. The following ties were taken:

Spk & W NW side PP	NE	73.5'
Spk & W S side CFP	E	42.0'
Concrete nail	W	10.0'
Concrete nail	S	10.0'
Co. PI 5/8" diameter	N	6.0'

1991 Jones, Haugh & Smith crew under the direction of John Schulte IV, County Surveyor, dug with County backhoe on centerline of north-south road in line with fence east. Uncovered a harrison cast iron monument over two 5/8" diameter irons extending 4 feet below road surface. Found no further evidence of public land survey corner. Reset cast iron monument found.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

"D" p39
"A" p65 TIEBOOK Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E 1/4 Corner of Section 11, Township 103, Range 16, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☑ On 4-22-82 (DATE) found a 6" x 8" x 4" SPLIT FLD. STONE WITH POINT UP

☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☑ On 4-22-82 (DATE) placed a 5/8"ø x 24" LONG IRON - CAPPED RLS 13807, OVER FLD STONE.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 4-26-82

Registration No. 13807

☑ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19__

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

