Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

S 1/4 Corner of Section 10, Township 103N Range 16W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch

☐ On 1-6-95 (DATE) found a Corner Fence Post

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 1-6-95 (DATE) placed a 5/8 iron at base rotted CFP, fence lines E-W-S

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

SIGNATURE _____ DATE 2-24-95

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 11 a M. on the 24 day of February A.D., 1995

COUNTY RECORDER Charles Enger

By Meryl A Taylor, Deputy

DOCUMENT NO. 435086

M.H.D. FORM NO. 2105

Book 86 Page 254

STATEMENT OF EVIDENCE

S 1/4 cor Sec 10-103-16

This corner was originally established by Deputy Surveyor John Quigley of the U.S. General Land Office in 1853. The government notes show this corner was marked with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

No information was available from the above sources.

1995 Jones, Haugh & Smith Inc personnel under the direction of John H. Schulte IV, RLS 13807, found a rotted corner fence post at an intersection of fence lines to the east, west and south. The rotted corner fence post was accepted as the best evidence of the public land survey corner and a 5/8" iron was set at the base of the rotted corner fence post. Electronic surveying equipment was then used to measure the distances to the southwest and southeast corners as well as to the center of Section 10. The distances are as follows:

2646.91' to the southwest corner
2656.54' to the southeast corner
2647.04' to the center of Section 10

For electronic survey data and analysis contact the firm of Jones, Haugh & Smith Inc.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

BOOK 86 PAGE 255