Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E 1/4 Corner of Section 26, Township 103N Range 16W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch

☐ On 05/12/1998 (DATE) found a –

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 05/12/1998 (DATE) placed a CAST IRON MOUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

_____ (SIGNATURE) 6-1-98 (DATE)

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19___

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

E 1/4 Cor Sec 26-103-16

This corner was originally established by Deputy Surveyor John Quigley of the U.S. General Land Office in 1853. The government notes show a wood post was set with mound of earth and trench.

The following were contacted for section corner information.

Mower County Highway Dept.
Mower County Recorder
Tucker Land Surveying

No record of this corner was obtained from the above mentioned offices.

1998 Jones Haugh and Smith crew, under direction of John Schulte, Mower County Surveyor RLS 13807, dug by hand at the centerline of CSAH No. 7 and in line with line fence east and at the location of patch in bituminous surface made by backhoe following excavation of section corner. Located an aluminum monument at this location. Left monument as found.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

For electronic survey data and analysis, contact the firm of Jones, Haugh and Smith Inc.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 26, Township 103N, Range 16W, 5 P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

On 4-12-89 found A .9' N-S BY .75' E-W BY .55' HIGH STONE DOWN 4'

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

On 4-12-89 placed A CTY. MON. ON A 24" BY 3/4" REBAR OVER STONE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald J. Olson (Signature) 7-25-89 (Date)

Registration No. 11009

☒ Land Surveyor ☐ Prof Engineer
☐ County Surveyor ☐ County Engineer

Zenk•Read•Trygstad & ASSOCIATES, INC.
Engineers/Architects/Land Surveyors/Planners
Box 689, Albert Lea, MN 56007 507/373-0689

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Recorders office at _____.M. on the ____ day of _____ A.D., 19___.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

EAST QUARTER CORNER SECTION 26 TOWNSHIP 103 NORTH RANGE 16 WEST 5TH P.M.

July, 1853 — John Quigley, Deputy Surveyor, set post for corner and built mound with trench per instructions and at center deposited hand full of small stones. SE planted Osage Orange Seeds during the original Public Land Survey.

Mower County Engineer's plans show a fence line east and west near the corner. No monument was shown.

April 12, 1989 — Ronald J. Olson, RLS 11009, excavated with a backhoe 4 feet north to 4 feet south of fence lines by 1.3 feet West to 3.7 feet East of the road centerline and found a 10 inch by 9 inch by 8 inch high stone near a 2inch piece of cut and charred stake 5 feet below the surface in mottled soil at the road centerline and the fence lines E-W. An 11 inch by 8 inch by 7 inch stone was found down 4 feet and a rebar in concrete was found over the stone 2.2 feet down. A 1 inch by 2 inch hub was found on the north side of the rebar. The stone was reset and a 3/4 inch by 18 inch pipe was placed on the west edge of the stone.

An analysis of the record data gives no indication of the origin of the stone. The location of the stone has been perpetuated over the years as evidenced by the additional monuments above it and it agrees with the lines of occupation. The rebar in concrete is typical of monuments placed by the County Engineer during road construction. The Stone is accepted as marking the location of the original Public Land Survey Corner