Index No. P 35, "F"
P 108, "N"

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

N1/4 Corner of Section 1, Township 103N Range 18W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On NOV. 1991 (DATE) found a CFP AND A FOUR WAY FENCE INTERSECTION

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On NOV. 1991 (DATE) placed a CAST IRON MONUMENT ON NORTH SIDE OF CFP

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE 4-30-93 DATE

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 3 P.M. on the 4 day of May A.D., 1993

COUNTY RECORDER Edwards Engen

By Marlene Morton, Deputy

DOCUMENT NO. 420483

Bk 79 Misc Pg 332

M.H.D. FORM NO. 2105

BOOK 79 PAGE 332

STATEMENT OF EVIDENCE

N 1/4 corner Section 1-103-18

This corner was originally established by Deputy Surveyor J.B. Reyman of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench. The following ties were taken:

7" Burr Oak	S 31 3/4° E	252 links (166.32 ft)
15" Burr Oak	S 71° W	910 links (600.60 ft)

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1884 Clausen, Mower County Surveyor, found a government post at the N 1/4 of Section 1.

1887 Clausen, Mower County Surveyor, found a government post at the S 1/4 Section 36-104-18.

1991 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, Reg. No. 13807, set a cast iron monument on the north side of a corner fence post at a 4-way fence intersection which runs north-south and east-west. The corner fence post at the 4-way fence intersection is considered best evidence of the location of the original public land survey corner.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

BOOK 79 PAGE 333

Jones & Haugh