Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

S1/4 Corner of Section 14, Township 104N Range 16W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-24-93 (DATE) found a SPIKE AND A 6"ø×18" CONC MONUMENT WITH IRON IN CNT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-24-93 (DATE) placed a CIM OVER CONC MONUMENT FOUND

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 6-11-93

Registration No. 13007

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 10 A.M. on the 21 day of June A.D., 1993

COUNTY RECORDER Chandra Ensgen

By Marlene Manton, Deputy

DOCUMENT NO. 421598

Bk 79 Misc Pg 600

M.H.D. FORM NO. 2105 BOOK 79 PAGE 600

STATEMENT OF EVIDENCE

S 1/4 cor Sec 14-104-16

This corner was originally established by Deputy Surveyor John Fitzpatrick of the U.S. General Land Office in 1853. The government notes show a wood post and stone were set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of the perpetuation of the original public land survey corner.

1943 Mower County Highway Department Book 1 and the County State Aid HIghway No. 1 Road Plans indicate a concrete monument at this corner.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, RLS 13807, dug a 3'x3'x6' hole on the centerline centerline of County State Aid Highway No. 1 and township road running north. We found a 4" long spike four inches below road surface and a 6" diameter x 18" concrete monument with iron in center three feet below spike found. The monument found is in agreement with the records. Therefore we accepted concrete monument found as the perpetuation of the original public land survey corner and set a cast iron monument near road surface and above monument found.

The monument found and cast iron monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

BOOK 79 PAGE 601