P. 60

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

N1/4 Corner of Section 5, Township 104N Range 17W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 6-7-93 (DATE) found a 10" x 24" LONG FIELD STONE

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 6-7-93 (DATE) placed a 5/8"ø x 16" IRON AND A CAST MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 7-26-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 8 A.M. on the 28 day of July A.D., 1993

COUNTY RECORDER Grandon Enger

By Marlene Martin, Deputy

DOCUMENT NO. 122591

Bk 80 Misc Pg 394

MLD. FORM NO. 2105 BOOK 80 PAGE 394

STATEMENT OF EVIDENCE

N 1/4 cor Sec 5-104-17

This corner was originally established by Deputy Surveyor Elisha S. Norris of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1890 Clausen, Mower County Surveyor, notes indicate a government post at this corner.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, RLS 13807, dug with the county backhoe a 5'x3'x12' long hole on the centerline of the east-west township road and in line with fence running south. We found a 10" diameter x 24" long pointed field stone at a depth of 2.4 feet which rested in virgin soil and also in line with fence running south and centerline of township road. We continued digging to clay soil and found no evidence of the original public land survey corner. Therefore we accepted stone found as the perpetuation of the original public land survey corner and placed a cast iron monument near road surface above stone found.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.