Index No. _____ "U" P.60

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NE Corner of Section 6, Township 104N Range 17W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 9-3-93 (DATE) found a 5/8"ø x 16" IRON CAPPED RLS NO. 13807 OVER A 6"ø CONC. MONUMENT WITH 1/2"ø IRON IN CENTER

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 9-3-93 (DATE) placed a LEFT MONUMENT AS FOUND

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 9-30-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of Mower

I hereby certify that this document was filed in the County Rec. office at 11 A.M. on the 1 day of October A.D., 19 93

COUNTY RECORDER Chandler Engen

By Marlene Marton, Deputy

DOCUMENT NO. 423994

By St of Misc. Pg. 177

M.H.D. FORM NO. 2105

BOOK R1 PAGE 177

STATEMENT OF EVIDENCE

NE corner Section 6-104-17

This corner was originally established by Deputy Surveyor Elisha S. Norris of the U.S. General Land Office in 1853. The government notes show a wood post and stone were set with a mound of earth and trench.

The following were contacted for section corner information:
- Mower County Highway Department
- Mower County Recorder
- Zenk Engineering
- Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1890 Clausen, Mower County Surveyor, notes indicate a post at this location.

1925 Mower County Highway Department Road Plans indicate this corner would be resting in pond.

1945 Mower County Highway Department Road Plans indicate a corner monument inplace at this corner.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, Reg. No. 13807, dug a hole 2.5 feet deep and found a 6" diameter concrete monument with 1/2" diameter iron in center. Monument found has been accepted on the section corner for 45 years more or less, therefore we left monument as found and set a 5/8" diameter x 16" iron capped RLS 13807 near road surface above monument found.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

BOOK 81 PAGE 172