Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SW Corner of Section 29, Township 104N, Range 18 W, 5TH P.M.

STATE OF MINNESOTA, County of Mower


At the corner location shown on the sketch:

☒ On 3-17-86 (DATE) found a cast iron monument 1.5' below road surface.

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 3-17-86 (DATE) placed a cast iron monument on road surface over monument found.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 7-30-91

Registration No. 13807

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

SW corner Sec. 29-104-18

This corner was originally established by Deputy Surveyor William Anderson of the U.S. General Land Survey Office in 1854. The government notes show this corner was marked with a post with a trench and the following ties were taken:

14" Burr Oak	S 33 W	90 links	(59.40')
6" Burr Oak	N 89 E	265 links	(174.90')

The following were contacted for section corner information:

Mower County Engineering Department
Mower County Recorders Office

Book 'A' in the Mower County Engineer's Office shows a magnetic corner inplace. Ties were taken and recorded as follows:
54.4 feet South to PP 51.2 feet North to Conduit on PP

1970 County State Aid Highway No. 26 road plans show a cast iron monument inplace.

1986 Jones, Haugh & Smith crew dug and found a cast iron monument 1.5 feet below road surface on centerline east-west roads and 20 feet more or less, west of centerline driveway south. Placed a cast iron head over a 5/8" diameter iron at road surface. Monuments found were left inplace.

Corner found fits occupation, road centerlines and past records and is accepted as best evidence of a perpetuation of the public land survey corner.

For electronic survey data and analysis contact the firm of Jones, Haugh & Smith Inc.