Revised

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

N1/4 Corner of Section 31, Township 104N Range 14W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-25-93 (DATE) found a 3/4"ø x 16" IRON AND A 6"ø x 18" CONC MON. WITH IRON IN CNT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-25-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ SIGNATURE _____ DATE

Registration No. _____

☐ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

N 1/4 corner Section 31-104-14

This corner was originally established by Deputy Surveyor John Taylor of the U.S. General Land Office in 1854. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Recorder's Office
Mower County Highway Department
Zenk Engineering
Tucker Land Surveying

1930 Mower County Grading Plans show a concrete monument inplace at Sta 0+00 4.8' south of centerline PI and the following ties were taken:
91.2' NW to TP
67.2' SW to fence post

1938 Book 'A' in the Office of the Mower County Engineer shows a concrete monument 4.8' south of centerline and the following ties were taken:
42.1' SE to Cottonwood
67.2' SW to fence post
91.2' NW to TP
82.9' NE to north end culvert

1965 Book 'A' in the Office of the Mower County Engineer shows a monument found 4.8' south of the centerline CSAH #1 and the following ties were taken:
55.5' SW to CFP
47.8' SW to PP
110.5' NW to TP

1991 Jones, Haugh & Smith Inc crew under the direction of John Schulte, County Surveyor, dug with the County backhoe 4.8' south of the centerline CSAH #1 in line with centerline north-south and found no evidence of public land survey corner or concrete monument recorded in County records. Therefore dug with backhoe on centerline centerline and uncovered a 1/2" diameter iron cast in the center of a 6" diameter concrete monument and established position of corner on centerline of north-south road 4.8' south of centerline PI as last recorded in Book 'A' in 1965. A cast iron monument was set on road surface and a capped 5/8" diameter iron RLS 13807 was set over concrete monument at centerline PI.

The monument found fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

For electronic survey data & analysis contact the firm of Jones, Haugh & Smith Inc.