CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 6, Township 102N, Range 17W, 5 P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

On 9-4-90 found 1/2" BAR (REMOVED DURING EXCAVATION)

☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)

On 9-4-90 placed 3/4" REBAR AND COUNTY CAP

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald A. Olson — Signature

11-6-90 — Date

Registration No. 11009

☒ Land Surveyor ☐ Prof Engineer

☐ County Surveyor ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Recorders office at _____ .M. on the _____ day of _____ A.D., 19___.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE

East Quarter Corner Section 6, Township 102 North, Range 17 West, 5th P.M.

September, 1854	William Anderson, Deputy Surveyor, set post at quarter section corner during the original Public Land Survey.
1957	Page 20 of Mower County Surveyors Record shows ties to monument.
1972	Mower County Engineers Plans show ties to monument.
September 4, 1990	Zenk Read Trygstad & Associates, Inc. excavated with a backhoe, a trench 4 feet North to 3 feet South of center line and 4 feet west to 4 feet east of the fence line to the North and 4.5 feet deep and found a 1" bar 2.8 feet below the surface on center line. An analysis of the record shows no indication of the origin of the bar. The bar agrees with the occupation lines and has been maintained by the County as the corner for over 33 years. The bar is accepted as marking the location of the original Public Land Survey Corner.