P 108 Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E. 1/4 Corner of Section 16, Township 103, Range 17, 5th P.M.

STATE OF MINNESOTA, County of Mower


At the corner location shown on the sketch:

☐ On _____ (DATE) found a _____

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On Nov. 20, 1978 (DATE) placed a Chiselled "X" in concrete

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald J. Olson (SIGNATURE) 3-13-80 (DATE)

Registration No. 11009

☒ Land Surveyor, ☒ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the Recorder's office at 3:00 P.M. on the 13 day of March A.D., 1980

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. 343775

M.H.D. FORM NO. 2105

Statement of Evidence:

EAST QUARTER CORNER SECTION 16, TOWNSHIP 103 NORTH, RANGE 17 WEST, 5 P.M.

1854 William Anderson, Deputy Surveyor, set the corner in the original Public Land Survey.

1937 Minnesota Department of Transportation graded T.H. 56 at the corner and no evidence of the corner was indicated.

1973 Minnesota Department of Transportation regraded and placed concrete pavement on T.H. 56. No evidence of the corner was found.

1978 Zenk Engineering searched the area at the location of corner indicated by electronic measurement with a magnetic locator and no evidence of the corner was found.

An analysis of the record data and electronic survey data gives no indication of monument perpetuation for over 40 years. The corner was set on the extension of the fence of the E-W 1/4 line in Section 16 on the centerline of T.H. 56. The occupation lines in Section 15 & 16 agree with this location.

For details of the analysis and electronic survey data contact Zenk Engineering, Inc., Albert Lea, Minnesota 56007