E¼ cor SEC. 28-101-16

9-14-90 JHS crew Dug at Location of Field Division West and E-W Tup Rd and Instructed by Paul Schreiden Area Farmer for 70 yrs. his Testimony says corner was destroyed by Corse cat on Tup, That Fence was at Location of Large cotton wood Tree on East side of Road

"Note" No corner was set at this Time.

JHS crew set corner by using ⅟₁₆th Line Fence to the South, East side. 1335.0 From SE cor. Double ⅟₁₆th Line Outer and set corner at 2670.0 From SE cor. Corner Fits Field Division West and Large Cotton wood East set ⅝"x16" Iron with Cast Iron Iron Outer. .60± Below Road Surface.

6-21-02 Cloudy 75° HLS SAT

