NE COR Sec. 28-101-16

cert. Filed 1-23-91 by JHS

Dug with Co. backhoe and uncovered a 3/4"Ø x 15" iron 1.0' below road surface continued digging and found no further evidence of PLS corner or a perpetuation thereof.

Placed capped 5/8"Ø iron at location of 3/4"Ø iron.

SPK & W PP NW 53.0'
" " CFP SW 62.3'
" " CFP NE 53.05'

Cloudy, Windy 50 9-14-90 DRR SAW √28

