8-01-02
cloudy
80°
HLS
SAT

53

SE¼ cor SEC. 32-102-17

NO INFORMATION FOUND IN MOWER Co. CORNER RECORDS

JHS CREW Dug with MOWER Co. BACKHOE ON ℄ of E-W TWP Rd AND ℄ of N-S TWP Rd.

Dug 10'X10' HOLE 5.0'± DEEP down to clay in SOIL AND FOUND NO EVIDENCE of PLS cor.

SET CORNER ON Straight BETWEEN SW cor & SE cor

CORNER FALLS in ℄ E-W TWP Rd AND ℄ of N-S TWP Rd.

SET ⅝"X16" IRON with ALUMINUM 160± BELOW Rd. SURFACE.

