5-9-91 DRR/RMK 4

N1 1/4 Cor Sec 28-102-17
cert. Filed 5-16-91 by JHS
Dug with Co. backhoe
on ℄ road for bituminous
overlay project #SAP 50-604-18

Dug a 8'x8'x7' deep
hole and uncovered
a large sand deposit
3' wide 6' long on ℄
road appears corner
may have been dug
for before cont. digging
and uncovered old
monkey wrench setting
vertical 4.5' deep cont
digging and found
rotted post bent over
under location of
wrench, assumed
wrench to have been
set over post. Placed
clm on road surface
at same location
of wrench found

-Took wrench home-

