NW cor SEC 31-102-17

No Information Found in Mower Co. Corner Records.

JHS Crew Dag with Mower in Backhoe, Uncovered Rock at 2.0'± Deep. Rock Fits ℄ of Twp Rd. and Line Fence West. Placed Capped 5/8" Iron on North side of Rock Found.

Set 5/8" x 16" Iron with Alum Mon. over Rock Found. -.60 ±. Below Road Surface.

8-22-02
Cloudy
75°
HLS
SAT
50

