10-26-94 CLEAR 60° ✓ HLS JSR 10

NE cor SEC. 9 - T103N - R. 16W

Cert. Filed 3-3-95 by JHS

JHS CREW dug with County Backhoe on ℄ of Road and in line with Line Fence West.

Found 6" x 14" Pointed Rock on ℄ of Road & in line with Line Fence West, 2.2' below Road Surface. Continued digging and found no further evidence.

Excepted Rock as true corner placed capped 5/8" ø Iron No. 7380? on North side of Rock Found.

Place capped 5/8" ø Iron over Rock Found 4" Below Road Surface.

HLS & JPA

12-16-98 Set Cast Iron Mon over 5/8" ø

