SW COR SEC. 11 – T103N R.16W

Cert Filed 2-21-95 by JHS

JHS CREW dug with Coundy BACKHOE ON CORNER of LINE FENCE WEST AND LINE FENCE North

Found 1½" SHAFT IN CONC. 1' BELOW GROUND SURFACE.

PLACED CAPPED 5/8" ø IRON No.13807 ON North SIDE of SHAFT, AND 5/8" ø IRON with CAP OVER SHAFT Found 4" BELOW SURFACE.

7-26-05 NEW TIES SET.

10-26-94
CLEAR
60°

HLS ✓
JSR

14.

