7-13-89

68

E¼ Cor Sec 2-103-18

Dug with Co. backhoe on ℄ N-S road in line with fence E-W and uncovered a 4" dia. charred post 3' long in virgin soil 2' deep placed a 5/8" ϕ iron on north side of post and a CIM near road surface above charred post

