5 1/4 SEC 1-103-18

Wayne Claasen Engr.
+ Surveying, Inc.
Waterloo, IA

4-6-99 Found a CIM in the centerline of Co Rds, flush with road surface.

2-13-09 Reset mag nail @ cor ≈ GPS

9/11/12 MDH Set Survey Marker Flush.
Set (2) Magnails as ties on fogline to NE & NW @ 50'.

4-6-99

52

