
7-19-91 DRR V3.

S1/4 Cor Sec 26-104-17

Dug with Co. backhoe on ℄ E-W road in line with fence north & found nothing

Defl. in Co. Road at this point used ℄ E-W Road in line with fences as best evidence and set CIM



Corner Cert. filed 8-12-91 (JAS)

3/4/2005 Dug 1.5' below ~~se~~ new surface Fd 5/8" Rebar No CAP. Tie Set CAP @ Surface Re tied corner