N ¼ Cor. Sec. 33-104-18

Cert. Filed 7-30-91 by JHS

Dug at location of good signal with metal loc. and uncovered a conc. nail & W with flagging 0.5 deep found no further evidence. 1988± RAY Tucker RLS dug with Co. backhoe before overlay project all records were lost and corner assumed destroyed by a meathead position of conc. nail & W fits occupation on ℄℄ N-S-E-W roads and agress with 1930± grading project and placed a ½" octagon iron at location of concrete nail & W.

12-5-90 DRR
PC 25° MLG ✓41

