W1/4 Cor Sec 15-101-14
cert. Filed 5-16-91 by JHS
Dug with Co. backhoe on ℄ Rd for overlay project CP 50-91-08-14

Dug a 4x10x5' deep hole a found no evidence of PLS corner or Perpetuation of accepted fence lines E-W and ℄ N-S road as best evidence and set CIM on road surface

5-11-04 CPV EJL

Reset Monument after Regrading Project. Set a survey Pin @ this location Using GPS.

5-7-91 PC 45° DRR/RMK 1

